

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, August 16, 2012

Kalamazoo River / Enbridge Spill



1. Morrow Lake southeastern cove area where sheen was observed.



2. Morrow Lake southeastern cove sheen was observed.



3. Morrow Lake Delta observed crews removing debris from Boom E.



4. Morrow Lake Delta observed crews removing debris from Boom C.



5. MP36.5 RDB area where sheen was observed.



6. MP36.5 RDB sheen was observed.



7. MP36.25 LDB area where sheen was observed.



8. MP36.25 LDB sheen was observed.



9. MP30.8 LDB no sheen observed.



10. MP28.25 Oxbow observed crew performing monthly sediment trap monitoring.



11. MP28.25 CSD observed being sampled.



12. MP28.25 observed sheen when boat reversed away from the bank.




13. Ceresco Dam downstream portage, observed sheen.



14. Ceresco Dam downstream portage, observed sheen.



15. Ceresco Dam, no decontamination station observed.



16. MP5.25 – MP5.5 LDB area where sheen was observed.



17. MP5.25 – MP5.5 LDB sheen was observed.



18. MP5.25 – MP5.5 LDB sheen was observed.



19. MP5.63 LDB area where sheen was observed.



20. MP5.63 LDB sheen was observed.



21. MP5.63 LDB area where sheen was observed.



22. Ceresco Dam control point boom observed sheen and debris collecting along the boom.



23. MP5.63 LDB observed the sweep boat operating.



24. MP4.5 just down from the former Island F observed sheen.



25. MP4.5 just down from the former Island F observed sheen.



26. MP4.5 just down from the former Island F observed sheen when the boat reversed out of the area.



27. MP10.75 sheen observed.



28. MP10.75 sheen observed.